26-Jun-03

Issue#	Issue	Coordination	Lead Agency
S5	Lack of system coordination between emergency response agencies	3	All
eneral Location	n: System wide		
ecommendation	as Implement recommendations developed as part of the Mankato Area TOCCs.		
S15	Segment safety BEC CSAH 17	2	Blue Earth County
General Location	n: BEC CSAH 17 from TH 22 to TH 60		
Recommendation	as This segment of old TH 14 will be upgraded in the future using turnback funds. T is one of the busier facilities in the region; therefore, good access spacing, should and turn lanes should be provided.		
S16	Segment safety BEC CSAH 5	2	Blue Earth County
General Location	n: BEC CSAH 5 - TH 14 to Lind Street		
Recommendation	as City and BEC to review signing, access locations, transition in number of lanes an enforcement efforts. Consider rebuilding to current standards.		
SY12	Need for a BEC CSAH 2 extension (between TH 22 and CSAH 5)	2	Blue Earth County
General Location	n: CSAH 2 near the Blue Earth County and Le Sueur County border		
Recommendation	as Extend BEC CSAH 2 between TH 22 and CSAH 5.		
03/2	DEC COAT 10		DI E 41 C
SY3	BEC CSAH 12 extension	3	Blue Earth County
General Location	n: Existing end of BEC CSAH 12 to TH 14		
Recommendation	as Extend BEC CSAH 12 to the south to connect with TH 14. A study identifying a preferred location (which side of the railroad) should be undertaken.		
O2	Fringe area growth management	3	Blue Earth County and Nicollet County
	n: Townships surrounding Mankato and North Mankato		
General Location	r		

26-Jun-03

Issue#	Issue	Coordination	Lead Agency
C3	Congestion on Madison Avenue	3	City of Mankato
General Locatio	n: Madison Avenue from Riverfront Drive to TH 22		
Recommendatio	ns Work on getting Victory Drive connection and Adams Street connection in place This should provide options and reduce volumes through most congested intersections.		
M2	Lack of rural transit	2	City of Mankato
General Locatio	n: Region wide		
Recommendatio	ns Review the feasibility of rural transit in five to seven years to determine if the demand for this service has increased.		
011	Lack of coordination between transit providers	3	City of Mankato
General Locatio	n: System wide		
Recommendatio	ns Mankato Heartland Express should invite other transit providers and medical transproviders to an annual meeting where the agencies, users and businesses can ident services provided and look for opportunities to coordinate services.		
O12	More convenient common transfer location for local and regional transit service	3	City of Mankato
General Locatio	n: Not determined		
Recommendatio	ns Based on the City of Mankato's Transit Study, one central transfer location shoul identified for rural trips to connect with the existing Mankato transit system for movement within Mankato.		
O5	Access to ISJ Hospital	1	City of Mankato
General Locatio	n: Near ISJ Hospital		
Recommendatio	ns Consider removing on-street parking on Dane Street and Dickinson Street. Also explore adding intersections at Belle Avenue, Marsh Street, Andrews Drive, Emel Lane and Main Street. A traffic study should be used to analyze the feasibility of these changes.		
S21	Trail connection between BEC CSAH 90 and MSU	3	City of Mankato
General Locatio	n: Along BEC CSAH 8 (Monks Ave.) from BEC CSAH 90 to BEC CSAH 60 (Stadiu Drive)		

26-Jun-03

	Issue	Coordination	Lead Agency
S31	Segment safety Madison Avenue	2	City of Mankato
General Locatio	on: Madison Avenue - from Long Street to Victory Drive		
ecommendation	ns Segment has more local access than other portions of Madison Avenue. Develop plan for access consolidation or consider a median extension.		
SY6	Lack of north/south routes (North Mankato industrial area)	2	City of North Mankato
General Locatio	n: North Mankato industrial area		
Pecommendation	ns Planned growth should access local collector streets, not major routes. Existing roadways should accommodate the new developments. North/South routes should explored to support Nicollet CSAH 13 and Lor Ray Drive.		
SY7	Need for improvements to Timm Road	1	City of North Mankato
	n: Timm Road		
ieneral Locatio	7. Timm Roug		
	ns Improve as development occurs.		
		2	Mn/DOT
C4	ns Improve as development occurs.	2	Mn/DOT
C4 General Locatio	Intersection capacity problems along TH 22 (long waits)	2	Mn/DOT
C4 General Locatio	Intersection capacity problems along TH 22 (long waits) on: TH 22 from Hoffman Rd. to TH 14 ns Develop alternative routes to TH 22 to provide alternate for local traffic. Provi adequate lane geometry on side streets (additional lanes to accommodate peak	2	Mn/DOT
C4 General Location Recommendation CS8	Intersection capacity problems along TH 22 (long waits) m: TH 22 from Hoffman Rd. to TH 14 ns Develop alternative routes to TH 22 to provide alternate for local traffic. Provi adequate lane geometry on side streets (additional lanes to accommodate peak flows). Add double left turn lanes at key intersections.		
C4 General Locatio CS8 General Locatio	Intersection capacity problems along TH 22 (long waits) m: TH 22 from Hoffman Rd. to TH 14 ms Develop alternative routes to TH 22 to provide alternate for local traffic. Provi adequate lane geometry on side streets (additional lanes to accommodate peak flows). Add double left turn lanes at key intersections. Number of traffic signals on major roadways (i.e., TH 22, TH 169, etc.)		
C4 General Location CS8 General Location	Intersection capacity problems along TH 22 (long waits) In: TH 22 from Hoffman Rd. to TH 14 Ins Develop alternative routes to TH 22 to provide alternate for local traffic. Provi adequate lane geometry on side streets (additional lanes to accommodate peak flows). Add double left turn lanes at key intersections. Number of traffic signals on major roadways (i.e., TH 22, TH 169, etc.) In: No location specified Ins Collector streets are needed adjacent to arterials to limit local access and reduce through traffic interruptions. Consider additional timing plans to better address	3	
C4 General Location CS8 General Location CS8 General Location CS9	Intersection capacity problems along TH 22 (long waits) m: TH 22 from Hoffman Rd. to TH 14 ns Develop alternative routes to TH 22 to provide alternate for local traffic. Provi adequate lane geometry on side streets (additional lanes to accommodate peak flows). Add double left turn lanes at key intersections. Number of traffic signals on major roadways (i.e., TH 22, TH 169, etc.) m: No location specified ns Collector streets are needed adjacent to arterials to limit local access and reduce through traffic interruptions. Consider additional timing plans to better address special peak usage (seasonal conditions).	3	Mn/DOT

26-Jun-03

Issue#	Issue	Coordination	Lead Agency
S34	Intersection safety TH 169 near Dairy Queen	3	Mn/DOT
General Location	on: TH 169 near Dairy Queen (two miles north of TH 14)		
Recommendatio	ns Consider working with local units of government to remove Dairy Queen (close access).		
S35	Intersection safety TH 14 and TH 169 interchange	1	Mn/DOT
General Locatio	n: TH 14 and TH 169 interchange		
Recommendatio	ns Make recommended design improvements to the interchange.		
SY8	Need for pedestrian/bicycle trail connection along (along TH 22) from South Roto Hoffman Road	1	Mn/DOT
General Locatio	n: TH 22 - extending south out of Mankato		
Recommendatio	ns Add trail connection as development occurs.		
O15	Blowing and drifting snow along TH 14	3	Private - WisPak and Taylo

Corp.

General Location: North Mankato industrial area

Recommendations Mn/DOT to provide information to businesses; need to find private leader to take initiative.